

June 18, 1999.

Mr. Paul Dandrade Cumberland Farms Inc. 777 Dedham Street Canton, Massachusetts 02021-9118

RE:

Cumberland Farms Inc., Station # 4018 (VDEC Site# 98-2418), 661 Pine Street,

Burlington, VT - Subsurface Contaminant Investigation Report

Dear Mr. Dandrade:

Lincoln Applied Geology, Inc. (LAG) is pleased to present this Subsurface Investigation Report (SIR) for Cumberland Farms Inc. (CFI) Station # 4018 (VDEC Site # 98-2418) located at 661 Pine Street in Burlington, Vermont. In response to the discovery of gasoline contaminated soils and ground water during the replacement of the Underground Storage Tank (UST) system piping, the Vermont Department of Environmental Conservation (VDEC) Sites Management Section (SMS) requested that a subsurface contaminant investigation be performed to determine the extent and magnitude of the petroleum contamination beneath the site. The requested contaminant investigation was performed by LAG between April 19 and May 7, 1999, and the SIR is attached. It includes well logs, monitoring data, ground water quality results, observations made during the sensitive receptor survey, and our conclusions and recommendations for the site.

Results of the investigation show that soil and ground water beneath the site has been impacted by low levels of petroleum contamination which was previously detected during the UST system piping assessment. Other than soil and ground water beneath the site, no contaminant impacts were detected in the CFI building ambient air space. Based on data collected during the subsurface investigation, we do not recommend that additional ground water monitor wells be installed at this time. However, we do recommend performing semiannual site monitoring and ground water sampling of the four on-site wells. This recommended sampling frequency will define the status of the limited contamination and enable us to determine the rate at which intrinsic bioremediation and natural attenuation processes are occurring beneath the site.

Please do not hesitate to call me or Richard S. Vandenberg, Project Manager, at (800) 477-4384, if you have any questions or comments regarding the attached report.

Sincerely,

Lincoln Applied Geology, Inc.

Jan D. Barnard

Jason S. Barnard

Geologist

JSB/jb enclosures

cc: Chuck Schwer

## Subsurface Investigation Report Cumberland Farms Inc., Station # 4018 661 Pine Street, Burlington, Vermont (VDEC Site #98-2418)

#### Prepared for:

Cumberland Farms Inc. 777 Dedham Street Canton, Massachusetts 02021-9118 Contact: Paul Dandrade Phone: (781) 828-4900 ext. 3416

#### Prepared by:

Lincoln Applied Geology, Inc. 163 Revell Drive Lincoln, Vermont 05443 Contact: Jason S. Barnard Phone: (802) 453-4384

June 18, 1999

Prepared by:

Jason S. Barnard Geologist Reviewed and Approved by:

Stephen Revell, CPG Senior Hÿdrogeologist

Lincoln Applied Geology, Inc Environmental Consultants

### **Table of Contents**

Executive Summary	i
Site Description	
Site History	
Monitor Well Installation	
Site Geology	
Site Survey and Monitoring	
Site Hydrogeology	
Water Quality Sampling	
Sensitive Receptor Survey	
Summary of Findings	
Recommendations	
Table 2 Table 3 Figure 1 Figure 2 Figure 3 Figure 4 Appendix A	Ground Water Elevation Well Headspace PID Assays Ground Water Quality Results General Location Map Detailed Site Map Ground Water Contour Map for May 7, 1999 Water Quality Map for May 7, 1999 Detailed Well Logs
Appendix B V	Vater Quality Laboratory Reports for May 7, 1999

#### **Executive Summary**

In April 1998, CFI and their subcontractors completed the removal, closure, and replacement of the underground storage tank (UST) system piping at CFI facility #4018, which is located at 661 Pine Street in Burlington, Vermont. Lincoln Applied Geology Inc. (LAG) conducted the assessment work between April 21 and April 29, 1998 and completed the UST closure report, which was submitted to the Vermont Department of Environmental Conservation (VDEC), Underground Storage Tank Program (USTP) in May 1998. During the assessment, all UST distribution and ventilation piping was noted in good condition with no apparent holes. However, during the assessment ground water containing a petroleum sheen was encountered three feet below grade near the dispenser island area.

During piping removal and assessment activities, excavated soils were screened with a photoionization detector (PID) for the presence of volatile organic compounds (VOCs). Approximately 40 cubic yards (yds³) of the most highly contaminated soils were removed (from the dispenser island area) and temporarily stockpiled on-site. Following VDEC approval, the gasoline contaminated soils were transported to the MTS Environmental, Inc. facility in Epsom New Hampshire where they were thermally treated. Based on the results of the April UST piping upgrade, the Sites Management Section (SMS) of the Vermont Department of Environmental Conservation (VDEC) requested that additional work be performed to further define the extent and magnitude of the soil and ground water contamination present beneath the site.

As a part of the requested additional work, LAG installed three monitor wells on-site on April 19, 1999 to define the extent and magnitude of the contamination remaining beneath the site. During the well installation an additional large diameter (8-inch) monitor well was discovered north of the UST area. Due to its location (downgradient), we elected to utilize this well and eliminate one of the originally proposed four borings. One well (MW-1) was installed upgradient, one well (MW-3) was installed downgradient, and one well (MW-4) was installed sidegradient of the UST and dispenser island areas. LAG also conducted a sensitive receptor survey by monitoring the ambient air space of the CFI building. Following installation, the wells were properly developed and sampled. A complete stadia survey was then performed on all monitor wells and pertinent site structures.

On May 7, 1999, LAG was on-site to measure static ground water levels, PID evaluate each monitor well headspace, and collect ground water samples from the three newly installed and one existing monitor wells. All samples were analyzed for the presence of volatile organic compounds (VOCs) by EPA 8021 and for total petroleum hydrocarbons (TPH) by EPA Method 8015.

Review of the May 7<sup>th</sup> water quality data shows that relatively low petroleum related VOCs and TPH concentrations were quantified above method detection limits in three out of the four wells sampled. Based on these findings and the lack of surrounding sensitive receptors, we do not recommend that additional ground water monitor wells be installed at this site. We do, however, recommended that site monitoring and ground water sampling of the four existing wells be performed on a semiannual basis. This sampling frequency will provide sufficient data to show contaminant concentration trends across the site.

#### Site Description

Cumberland Farms, Inc. (CFI) facility #4018 is located at 661 Pine Street in Burlington, Vermont (Figure 1). The property is bound by Lakeside Avenue to the north, Pine Street to the east, and commercial properties to the south and west (Figure 2). CFI's one-story, slab ongrade building is served by municipal water and sewer. Figure 2 is a Detailed Site Map showing pertinent features of the site.

#### Site History

CFI and their subcontractors completed the excavation, removal, and replacement of all UST system distribution piping in April 1998. During the work, LAG provided oversight and assessment of the piping and soils. The UST Permanent Closure Form, photoionization detector (PID) data, and photographs of the site were submitted by LAG to the Vermont Department of Environmental Conservation (VDEC), Underground Storage Tank Program (USTP) in a report dated May 5, 1998. During the work, ground water containing a petroleum sheen was encountered 3 feet below grade in the vicinity of the dispenser island area. In order to quantify the contaminant levels present, a ground water sample was collected. The analytical results indicated that ground water in the vicinity of the dispenser island area contained elevated levels of dissolved phase petroleum related constituents.

During the work, excavated soils were screened for the presence of VOCs using a properly calibrated photoionization detector (PID) equipped with a 10.2 electron volt lamp. Data collected during the UST piping upgrade indicated that soils in the vicinity of the two product dispensers contained elevated concentrations of VOCs. To accommodate the new distribution piping and appropriate backfill material, the most highly contaminated soils were removed from the dispenser island area. Approximately 40 cubic yards (yds³) of the most highly contaminated soils were removed from the excavation and ultimately disposed of at MTS Environmental in Epsom, New Hampshire. Due to the presence of contamination remaining in soils and ground water in the vicinity of the dispenser island, the SMS requested that additional work be performed to further define the extent and magnitude of the contamination beneath the site.

#### Monitor Well Installation

Three monitor wells (MW-1, MW-3, and MW-4) were drilled and installed using hollow stem auger drilling techniques on April 19, 1999 by T & K Drilling. During the drilling an additional monitor well was discovered downgradient of the UST area. As a result of this discovery, only three of the originally proposed four wells were installed. The locations of the four monitor wells are shown on Figure 2. A description of the sediments encountered during the drilling, monitor well construction details, and PID data from the split-spoon samples, are presented in the detailed well logs which are included as Appendix A.

#### Site Geology

Soils encountered during drilling include a fine to coarse sand and gravel, overlying a more dense, less permeable silt and/or very fine to fine sand. This material represents typical lake bottom sediments deposited following the last ice age approximately 10,000-12,000 years ago.

Review of the Centennial Geologic Map of Vermont (C.G. Doll, 1961) indicates that the



underlying bedrock is of the Monkton Quartzite formation (540 to 570 million years ago). The Monkton Quartzite formation consists of a red quartzite interbedded with white quartzite and thick sections of dolomite.

#### Site Survey and Monitoring

On April 19, 1999, LAG conducted a stadia survey of monitor wells MW-1, 2, 3, 4, and other site features pertinent to the subsurface investigation. On May 7th, LAG collected ground water level measurements from all monitor wells using an electronic interface probe capable of measuring 0.01 feet of free-floating petroleum product. LAG also assayed the headspace of each monitor well using a properly calibrated PID for the presence of petroleum related VOCs. Review of the collected data indicates that no free-floating petroleum product was present in any of the wells. The depth to ground water ranged between 3.04 feet (MW-4) and 5.15 feet (MW-2) across the site. A summary of ground water elevation data from May 7th is presented in Table 1, and PID assays are included in Table 2. Well headspace PID readings collected on May 7th were all at background (BG) levels. The collected data suggests that only a very limited amount of vadose zone contamination exists in the vicinity of the dispenser island area at the site.

#### Site Hydrogeology

Ground water elevation data from May 7th was used to develop a Ground Water Contour Map (Figure 3). Review of Figure 3 shows that ground water flows across the site in a northerly direction along a low to moderate gradient of 0.028 feet/foot.

#### Water Quality Sampling

On May 7, 1999, LAG collected water quality samples from monitor wells MW-1, 2, 3, and 4 using industry accepted methods. All samples were analyzed for the presence of VOCs via EPA Method 8021 and for total petroleum hydrocarbons (TPH) via EPA Method 8015 [gasoline range organics (GRO)] at Toxicon Laboratories Inc. in Bedford, Massachusetts.

The water quality results are summarized in Table 3 and are presented on the Water Quality Summary Map included as Figure 4. Copies of the laboratory reports are included as Appendix B. Review of Table 3, Figure 4, and Appendix B indicate that low concentrations of VOCs and TPH were present in three of the four wells sampled. The data shows that MW-3 and MW-4 contained total benzene, toluene, ethylbenzene, and xylene (BTEX) concentrations of 459 parts per billion (ppb) and 32.6 ppb, respectively. The sample collected from MW-2 contained 372 ppb of methyl-tert-butyl-ether (MTBE). The data also shows that no contaminant concentrations were present in MW-1 (most upgradient well) above method detection limits. Based on this water quality data, it is apparent that ground water beneath the site has been impacted by relatively low levels of petroleum related contamination. Did not be utility writers as requested in lette

#### Sensitive Receptor Survey

On April 19, 1999 LAG conducted a sensitive receptor survey of the site and surrounding properties. Potential sensitive receptors identified include only the indoor air of the CFI building. The CFI building and surrounding commercial buildings are all served by municipal water and sewer. Furthermore, indoor ambient air impacts to the CFI facility are highly unlikely because the building is constructed of a concrete slab on-grade. The collected data is summarized and



presented in **Table 2**. The data indicates that no PID readings above BG levels were present in the CFI building on April 19<sup>th</sup>.

Based upon these results, LAG strongly believes that there are no significant health related risks associated with the vapor and dissolved phase contamination present beneath the site. Furthermore, other than the low level detections identified in the ground water, the site does not pose a significant threat to any potntial sensitive receptors.

#### **Summary of Findings**

Based on the data collected, observations, and the evaluations presented, the following conditions exist at the site:

- 1. Low concentrations of dissolved phase gasoline contamination are present in ground water beneath the site.
- 2. The current dissolved phase contaminant plume does slightly extend beyond the existing monitor well configuration (MW-2). However, based on the commercial nature of surrounding properties, the relative low level of dissolved phase contamination on-site, and the lack of surrounding sensitive receptors, we do not believe that additional monitor wells are necessary at this time.
- 3. The elevated levels of dissolved phase contamination noted during the UST system upgrade remains localized in the vicinity of the dispenser island area.
- 4. A limited amount of vadose zone contamination continues to remain in soils in the vicinity of the dispenser island area.
- 5. No contaminant vapor impacts were present in the CFI building structure.

#### Recommendations

Based on these findings, the following recommendations are made:

- 1. No additional subsurface investigational work should be performed at this site, other than conducting the semiannual monitoring and sampling of the four existing wells. We believe that this sampling frequency will provide sufficient data to document the status of the low level contamination and help track on-going intrinsic biodremediation and natural attenuation.
- Prepare a summary report following our review of the data collected during the semiannual site monitoring and sampling events. A cost estimate to implement the semiannual site monitoring and ground water sampling is included as Appendix C.

FACHENTS/CUMBREND, FRM/BURLINGY/SUM0699, RPT



Project: Cumberland Farms, Inc. - Station # 4018

Location: Burlington, Vermont

Table 1 VDEC Site # 98-2418

Sheet 1 of 1

#### Ground Water Elevation/Product Level (feet)

Data Point	тос	05/07/99	 	
MW-1	100.00	96.58		
MW-2	97.83	92.68	 ·····-	
MW-3	97.52	93.84	 	
MW-4	97.44	94.40	 	

Dark Grey Cell = Inaccessible

Project: Cumberland Farms, Inc. - Station # 4018

Location: Burlington, Vermont

Table 2 VDEC Site # 98-4018

Sheet 1 of 1

### Photoionization Results (PID - ppm)

Data Point	04/19/99	05/07/99		,	····	
MW-1		BG				
MW-2		BG				
MW-3		BG	<u>.</u>			
MW-4		BG				
CFI Store	BG					
•			<del></del> <del></del>			

Project: Cumberland Farms Inc., Station # 4018

Location: Burlington, Vermont

Table 3 VDEC Site # 98-2418 Sheet 1 of 1

#### **Ground Water Quality Results (ppb)**

Data Point	Compound	05/07/99			
	Benzene	<2			
	Toluene	<2			
	Ethylbenzene	<2	·		
	Xylenes	<4			
	MTBE	<5		[	
MW-1	BTEX	<10			
	TPH 8015M	<0.02			
	BTEX + MTBE	<15			
	Benzene	<10			
	Toluene	<10			
	Ethylbenzene	<10			
	Xylenes	<20			
	MTBE	372			
MW-2	BTEX	<50			
	TPH 8015M	0.567			
	BTEX + MTBE	422			
	Benzene	294			
	Toluene	95.5			
	Ethylbenzene	<10			
	Xylenes	59.5	<del></del>		
	MTBE				
MW-3	BTEX	459			
	TPH 8015M	0.839			
	BTEX + MTBE				
	Benzene	<2			
	Toluene	<2			
	Ethylbenzene	<2		<u></u>	
	Xylenes	26.6			
	MTBE				
		~~ ~			
MW-4	BTEX	32.6		<del> </del>	
MW-4	BTEX TPH 8015M	32.6 0.065			
MW-4		0.065			


use 8021 b & April rapthalous, TMB

# Cumberland Farms, Inc. - Station #4018 SMS Site #98-2418 Burlington, Vermont




#### GENERAL LOCATION MAP

















Appendix A

Detailed Well Logs

#### **WELL LOG**

WELL:

MW-1

LOCATION:

CFI - Station #4018, 661 Pine Street, Burlington, VT

DRILLER:

T&K Drilling, Troy, NH

HYDROGEOLOGIST:

Rick Vandenburg, Lincoln Applied Geology, Inc.

DATE:

April 19, 1999

**Soils Description:** 

(BG =  $\underline{B}$ ackground [0.2], SL =  $\underline{S}$ aturated  $\underline{L}$ amp [>500], ppm =  $\underline{P}$ arts  $\underline{P}$ er  $\underline{M}$ illion)

<u>Depth</u>	<u>Description</u>	PID (ppm)
0 - 2'	Sand, tan to brown, fine to coarse; some gravel, fine; trace silt; sample dry.	2.7
2' - 12'	Silt, dark green; some sand, very fine to fine; (sample wet at 5 feet).	1.8 @ 5'-7' 1.0 @ 8'-10' 1.2 @ 10'-12'

#### Well Construction:

Bottom of Boring:

12' 12'

Bottom of Well:

6' - (4 -12') 2.0" sch 40 pvc, 0.020" slot

Well Screen: Solid Riser:

3.5 (0.5 - 4') 2.0" sch. 40 pvc

Sand Pack:

7' (3 - 10') #0 sand

Bentonite Seal:

1' (2 - 3')chips

Backfill:

1' (1 - 2') drill cuttings

Well Box:

cemented flush with grade

#### **WELL LOG**

WELL:

MW-3

LOCATION:

CFI - Station #4018, 661 Pine Street, Burlington, VT

DRILLER:

T&K Drilling, Troy, NH

HYDROGEOLOGIST:

Rick Vandenberg, Lincoln Applied Geology, Inc.

DATE:

April 19, 1999

**Soils Description:** 

(BG =  $\underline{B}$ ackground [0.2],  $\underline{S}$ L =  $\underline{S}$ aturated  $\underline{L}$ amp [>500],  $\underline{p}$ pm =  $\underline{P}$ arts  $\underline{P}$ er  $\underline{M}$ illion)

<u>Depth</u>	<u>Description</u>	PID (ppm)
0.5' - 2.5'	Dark brown to black debris, wood, coal, etc.; gravel, fine to coarse; some silt; some fine sand (dry)	BG
2.5' - 10'	Silt, light green; some sand, very fine; trace clay. (sample wet to saturated at 5' - 6')	BG @ 5'-7' BG @ 8'-10'

#### Well Construction:

Bottom of Boring:

10'

Bottom of Well:

10' 6' (4 - 10') 2.0 " sch. 40 pvc, 0.020" slot

Well Screen: Solid Riser:

3.5' (0.5 - 4') 2.0" sch. 40 pvc

Sand Pack:

7' (3 - 10') #0 sand

Bentonite Seal:

1 (2 - 3') chips

Backfill:

1 (1 - 2') drill cuttings

Well Box:

cemented flush with grade

#### **WELL LOG**

WELL:

MW-4

LOCATION:

CFI - Station #4018, 661 Pine Street,

DRILLER:

T&K Drilling, Troy, NH

HYDROGEOLOGIST:

Rick Vandenburg, Lincoln Applied Geology, Inc.

DATE:

April 19, 1999

**Soils Description:** 

(BG =  $\underline{B}$ ackground [0.2], SL =  $\underline{S}$ aturated  $\underline{L}$ amp [>500], ppm =  $\underline{P}$ arts  $\underline{P}$ er  $\underline{M}$ illion)

<u>Depth</u>	<u>Description</u>	PID (ppm)
0 - 0.5'	Gravel, fine to coarse, brown; sand, light green; trace coarse sand; sample dry	30
0.5' - 10'	Sand, very fine to fine; light green to light pink; some silt; trace clay.	40 @ 2' - 4' 12 @ 4' - 6' BG @ 6' - 8' BG @ 8' - 10'

#### Well Construction:

Bottom of Boring:

10'

Bottom of Well:

10'

Well Screen:

6' (4 - 10") 2.0' sch. 40 pvc. 0.020" slot

Solid Riser:

3.5' (0.5 - 4.0') 2.0" sch. 40 pvc

Sand Pack:

7' (3 - 10') #0 sand

Bentonite Seal:

1' (2 - 3') chips

Backfill:

1' (1 - 2') drill cuttings

Well Box:

cemented plush with grade

Appendix C

**Cost Estimate** 

#### Cumberland Farms, Inc. (CFI) 661 Pine Street, Burlington, Vermont VDEC #98-2418 10-Jun-99

# Cost Estimate for Semiannual Site Monitoring and Ground Water Sampling

### Task A. Ground Water Sampling (One Round)

Hydrogeologist/Site Manager -	0.5	hr(s) @	\$75.00	per hour	\$	37.50
Field Technician -	6	hr(s) @	\$45.00	per hour	\$	270.00
Disposable Bailer (1.5") -	4	· @	\$8.89	each	\$	35.56
EPA 8021b -	5	<u>@</u>	\$100.00	each	\$	500.00
Mileage -	125	mile(s) @	\$0.35	per mile	\$	43.75
Sampling Equipment -	1	day(s) @	\$110.00	per day	\$	110.00
				Subto	ai \$	996.81
				2X Year	iy \$	1,993.62
Description of Cummary Donort						

#### Task B. Preparation of Summary Report

Principal/Senior Hydrogeologist -	0.5	hr(s) @	\$90.00 per hour	\$ 45.00
Hydrogeologist/Site Manager -	1	hr(s) @	\$75.00 per hour	\$ 75.00
Geologist/Site Manager -	4	hr(s) @	\$55.00 per hour	\$ 220.00
Computer/CAD Technician -	2	hr(s) @	\$55.00 per hour	\$ 110.00
Administrative Assistant -	1.25	hr(s) @	\$35.00 per hour	\$ 43.75

Subtotal \$ 493.75

2X Yearly \$ 987.50

Yearly Total >>> \$ 2,981.12

Costs OR
- add PID survey of tilety crish along
Pin St. & Ish ish Are.

Appendix B

Laboratory Reports for May 7, 1999

TOXIKON CORP. REPORT Work Order # 99-05-206 Page 1 Received: 05/11/99 05/17/99 10:11:05 REPORT LINCOLN APPLIED GEOLOGY PREPARED TOXIKON CORPORATION BY 15 WIGGINS AVE TO REVELL DRIVE BEDFORD, MA 01730 LINCOLN, VT 05443 802-453-4384 FAX: 5399 ATTEN PAUL LEZBERG ATTEN RICK VANDENBERG CONTACT JOHNM PHONE (781)275-3330 CLIENT LINCOLN VT SAMPLES 5 MA CERT # M-MAO64: TRACE METALS, SULFATE, CYANIDE, RES. FREE COMPANY LINCOLN APPLIED GEOLOGY CHLORINE, Ca, TOTAL ALK., TDS, pH, THMs, VOC, PEST., NUTRIENTS. FACILITY REVELL DRIVE DEMAND. O&G. PHENOLICS, PCBs . CT DHS #PH-0563, NY #10778 LINCOLN, VT 05443 FL HRS E87143, NJ DEP 59538, NC DNR286, SC 88002, NH 204091-C. WORK ID CFI #4018 BURLINGTON, VT TAKEN 5/7/99 VERIFIED BY: CERT #MMA064 TRANS \_\_\_ TYPE WATER P.O. # CF1 INVOICE under separate cover TEST CODES and NAMES used on this workorder SAMPLE IDENTIFICATION

8021M VOL. ORG. COMP.

GRO GASOLINE RANGE ORGANICS

01 TRIP BLANK

02 MW-1 03 MW-4 04 MW-3 05 MW-2

 $\eta M$ :



REPORT

Work Order # 99-05-206

Results by Sample

SAMPLE ID TRIP BLANK

Received: 05/11/99

FRACTION <u>01A</u> TEST CODE <u>8021M</u> NAME <u>VOL. ORG. COMP.</u>

Date & Time Collected <u>05/07/99 09:00:00</u> Category <u>WATER</u>

	RESULT	LIMIT			
•					
Dichlorodifluoromethane	ND	2.0	Ethyl benzene	<u>ND</u>	2.0
Chloromethane	ND	2.0	1,1,1,2-Tetrachloroethane	ND	2.0
Vinyl Chloride	ND	2.0	m+p-Xylene	<u> ND</u>	2.0
Bromomethane	<u>ND</u>	5.0	o-Xylene	<u>ND</u>	2.0
Chloroethane	<u> ND</u>	2.0	Styrene	ND	2.0
Trichlorofluoromethane	ND	2.0	Isopropyl benzene	<u>ND</u>	<u>_2.0</u>
1,1-Dichloroethene	<u> ND</u>	2.0	Bromoform	<u>ND</u>	<u>2.0</u>
Methylene Chloride	ND	2.0	1,1,2,2-Tetrachloroethane	<u>ND</u>	2.0
trans-1,2-Dichloroethene	ND	2.0	1,2,3-Trichloropropane	<u></u>	2.0
1,1-Dichloroethane	ND.	2.0	n-Propyl benzene	<u>_ND</u>	<u>2.0</u>
2,2-Dichloropropane	<u>ND</u>	2.0	Bromobenzene	ND	2.0
cis-1,2-Dichloroethene	ND	2.0	1,3,5-Trimethyl benzene	<u>ND</u>	<u>2,0</u>
Chloroform	<u>ND</u>	2.0	2-Chlorotoluene	<u> </u>	2.0
Bromochloromethane	NĐ	2.0	4-Chlorotoluene	ND	2.0
1,1,1-Trichloroethane	ND	2.0	tert-Butyl benzene	<u>ND</u>	2.0
1,1-Dichloropropene	ND	2.0	1,2,4-Trimethylbenzene	ND	2,0
Carbon Tetrachloride	ND.	2.0	sec-Butylbenzene	ND	2,0
Benzene	ND	2.0	p-lsopropyltoluene	ND	2.0
1,2-Dichloroethane	ND	2.0	1,3-Dichlorobenzene	<u>ND</u>	<u>2.0</u>
Trichloroethene	<u>NO</u>	2.0	1,4-Dichlorobenzene	<u>ND</u>	2.0
1,2-Dichloropropane	ND	2.0	n-Butylbenzene	ND	2.0
Bromodichloromethane	ND	2.0	1,2-Dichlorobenzene	ND	<u>2.0</u>
Dibromomethane	ND	5.0	1,2-Dibromo-3-Chloropropane	ND	5.0
Toluene	<u> ND</u>	2.0	1,2,4-Trichlorobenzene	ND	2.0
1,1,2-Yrichloroethane	<u></u>	2.0	<b>Hexachlorobutadiene</b>	<u>ND</u>	2.0
Tetrachloroethene	<u>ND</u>	2.0	Naphthalene	<u>nd</u>	2.0
1,3-Dichloropropane	ND	2.0	1,2,3-Trichlorobenzene	<u>ND</u>	2.0
Dibromochloromethane	ND	2.0	Methyl-t-Butyl Ether	ND	5.0
1,2-Dibromoethane	<u>ND</u>	2.0			
Chlorobenzene	ND	2.0			
			all the British and a second s		

Notes and Definitions for this Report:

DATE RUN	<u>05/14/99</u>
ANALYST	JPM
INSTRUMENT	T
DILUTION	1
HINTTS	ue/I

Hard L

. . .

Page 3 Received: 05/11/99 TOXIKON CORP.

REPORT

Work Order # 99-05-206

Results by Sample

SAMPLE ID TRIP BLANK

FRACTION <u>01A</u> TEST CODE <u>GRO</u> NAME <u>GASOLINE RANGE ORGANICS</u>

Date & Time Collected <u>05/07/99 09:00:00</u> Category <u>MATER</u>

	8015 MODIFIED GRO
ALIPHATICS AROMATICS	ND   0.010   ND   0.010
- - -	
	Notes and Definitions for this Report:
	DATE RUN         05/12/99           ANALYST         CAL           INSTRUMENT         V5           DIL_ FACTOR         1           UNITS =         mg/L
•	ND = not detected at detection limit

WAR .

TOXIKON CORP. REPORT

Page 4 Received: 05/11/99

Results by Sample

SAMPLE ID HW-1	FRACTION <u>02A</u>	TEST CODE 8021M			
	Date & Time Col	lected <u>05/07/99 11</u>	<u>:00:00</u>	Category <u>WATER</u>	

	RESULT	LIMIT			
Dichlorodifluoromethane	ND	2.0	Ethyl benzene	<u> </u>	2.0
Chloromethane	ND	2.0	1,1,1,2-Tetrachloroethane	ND	2.0
Vinyl Chloride	<u>ND</u>	2.0	m+p-Xylene	<u> </u>	2.0
Bromomethane	<u>ND</u>	5.0	o-Xylene	<u>ND</u>	2.0
Chloroethane	<u>ND</u>	2.0	Styrene	ND	2.0
Trichlorofluoromethane	<u>ND</u>	2.0	Isopropyl benzene	ND	2.0
1,1-Dichloroethene	ND	2.0	Bromoform	<u>ND</u>	2.0
Methylene Chloride	ND	2.0	1,1,2,2-Tetrachloroethane	<u>ND</u>	2.0
trans-1,2-Dichloroethene	<u>ND</u>	2.0	1,2,3-Trichloropropane	<u>ND</u>	2.0
1,1-Dichloroethane	GN	2.0	n-Propyl benzene	ND	2.0
2,2-Dichloropropane	ND	2.0	Bromobenzene	<u>ND</u>	<u>2.0</u>
cis-1,2-Dichloroethene	ND	2.0	1,3,5-Trimethyl benzene	ND.	2.0
Chloroform	<u>ND</u>	2.0	2-Chlorotoluene	ND	<u>2.0</u>
Bromochloromethane	N <u>D</u>	2.0	4-Chlorotoluene	<u>ND</u>	2.0
1,1,1-Trichloroethane	ND	2.0	tert-Butyl benzene	ND	2.0
1,1-Dichloropropene	<u>ND</u>	2.0	1,2,4-Trimethylbenzene	<u>NO</u>	2.0
Carbon Tetrachloride	ND	2.0	sec-Butylbenzene	<u>ND</u>	2.0
Benzene	<u>CN</u>	2.0	p-Isopropyltoluene	<u>nd</u>	2.0
1,2-Dichloroethane	<u> ND</u>	2.0	1,3-Dichlorobenzene	<u> </u>	2.0
Irichloroethene	ND	2.0	1,4-Dichlorobenzene	- ND	2.0
1,2-Dichloropropane	<u>ND</u>	2.0	n-Butylbenzene	ND	2.0
Bromodichloromethane	ND	2.0	1,2-Dichlorobenzene	ND	2.0
Dibromomethane	ND	5.0	1,2-Dibromo-3-Chloropropane	ND	5.0
Toluene	ND	2.0	1,2,4-Trichlorobenzene	<u>ND</u>	2.0
1,1,2-Trichloroethane	ND	2.0	<b>Hexachlorobutadiene</b>	<u> </u>	2.0
Tetrachloroethene	ND.	2.0	Kaphthalene	<u> </u>	2.0
1,3-Dichloropropane	אס	2.0	1,2,3-Trichlorobenzene	ND	2.0
Dibromochloromethane	ND	2.0	Methyl-t-Butyl Ether	<u>ND</u>	5.0
1,2-Dibromoethane	ND	2.0	• .		
Chlorobenzene	ND	2.0			
			and the same		

Notes and Definitions for this Report:

DATE RUN 05/14/99 ANALYST JPH  MA .



Page 5	
Received:	05/11/99

TOXIKON CORP.

REPORT

Work Order # 99-05-206

Results by Sample

SAMPLE ID HU-1

FRACTION <u>O2A</u> TEST CODE <u>GRO</u> NAME <u>GASOLINE RANGE ORGANICS</u>

Date & Time Collected <u>05/07/99 11:00:00</u> Category <u>WATER</u>

8015 MODIFIED GRO RESULT LIMIT ND \_\_\_\_0.010 ALIPHATICS ND 0,010 AROMATICS Notes and Definitions for this Report: DATE RUN 05/12/99 CAL ANALYST INSTRUMENT DIL. FACTOR UNITS = mg/L ND = not detected at detection limit

Received: 05/11/99

Results by Sample

REPORT

SAMPLE ID MU-4 FRACTION 03A TEST CODE 8021M NAME VOL. ORG. COMP.

Date & Time Collected 05/07/99 11:25:00 Category WATER

	RESULT	LIMIT			
Dichlorodifluoromethane	ND	2.0	Ethyl benzene	ND	2.0
Chloromethane	DK D	2.0	1,1,1,2-Tetrachloroethane	<u> ND</u>	2.0
Vinyl Chloride	ND	2.0	m+p-Xylene	24.6	2.0
Bromomethane	ND	5.0	o-Xylene	<u>ND</u>	2.0
Chloroethane	NĐ	2.0	Styrene	<u> </u>	2.0
Trichlorofluoromethane	ND	2.0	Isopropyt benzene	<u>ND</u>	2.0
1,1-Dichloroethene	ND.	2.0	Bromoform	ND	2.0
Methylene Chloride	ND	2.0	1,1,2,2-Tetrachloroethane	ND.	2.0
trans-1,2-Dichloroethene	ND	2.0	1,2,3-Trichloropropane	ND	2.0
1,1-Dichloroethane	ND	2.0	n-Propyl benzene	<u>ND</u>	2.0
2,2-Dichloropropane	ND.	2.0	Bromobenzene	ND	2.0
cis-1,2-Dichloroethene	<u>ND</u>	2.0	1,3,5-Trimethyl benzene	<u>ND</u>	2.0
Chloroform	ND.	2.0	2-Chlorotoluene	<u>ND</u>	2.0
Bromochloromethane	ND	2.0	4-Chlorotoluene	ND	2.0
1,1,1-Trichloroethane	ND	2.0	tert-Butyl benzene	ND	2,0
1,1-Dichtoropropene	<u>ND</u>	2.0	1,2,4-Trimethylbenzene	12.5	2.0
Carbon Tetrachloride	<u> ND</u>	2.0	sec-Butyl benzene	<u>ND</u>	2.0
Benzene	ND	2.0	p-Isopropyltoluene	ND	2.0
1,2-Dichloroethane	ND	2.0	1,3-Dichtorobenzene	ND	
Trichloroethene	ND	2.0	1,4-Dichlorobenzene	<u> ND</u>	2.0
1,2-Dichloropropane	<u> </u>	2.0	n-Butylbenzene	ND	2.0
Bromodichloromethane	<u>ND</u>	2.0	1,2-Dichlorobenzene	<u>ND</u>	2.0
Dibromomethane	<u>ND</u>	5.0	1,2-Dibromo-3-Chloropropane	ND	<u>5.0</u>
Toluene	ND	2.0	1,2,4-Trichlorobenzene	<u>ND</u>	2.0
1,1,2-Trichloroethane	ND	2.0	Hexach Lorobutadiene	<u>ND</u>	2.0
Tetrachloroethene	<u>MD</u>	2.0	Naphthalene	<u>ND</u>	2.0
1,3-Dichloropropane	<u>ND</u>	2.0	1,2,3-Trichlorobenzene	<u>——₩Ď</u>	2.0
Dibromochloromethane	ND	2.0	Methyl-t-Butyl Ether	<u>NĐ</u>	<u>5.0</u>
1,2-Dibromoethane	<u>ND</u>	2.0			
Chlorobenzene	<u> </u>	2.0			
Note	es and Definit	ions for	this Report:		

DATE RUN 05/14/99

ANALYST JPM

INSTRUMENT D

DILUTION 1

UNITS Ug/L

WW The state



Page 7

TOXIKON CORP.

REPORT

Work Order # 99-05-206

Received: 05/11/99

Results by Sample

SAMPLE	ID	MLI-4	
410 H CC		<u> </u>	

FRACTION <u>03A</u> TEST CODE <u>GRO</u> NAME <u>GASOLINE RANGE ORGANICS</u>
Date & Time Collected <u>05/07/99 11:25:00</u> Category <u>WATER</u>

	8015 MODIFIED GRO
	RESULT LIMIT
	<u> </u>
ALIPHATICS	ND 0.010
AROMATICS	<u>0.055</u> <u>0.010</u>
_	
<u>-</u>	
_	
	Notes and Definitions for this Report:
	DATE RUN 05/12/99
	ANALYSY <u>CAL</u>
	INSTRUMENT V5
	DIL. FACTOR1
	UNITS = mg/L





TOXIKON CORP.

Received: 05/11/99

Page 8

Results by Sample

REPORT

SAMPLE ID MW-3 FRACTION <u>04A</u> TEST CODE <u>8021M</u> NAME <u>VOL. ORG. COMP.</u> Date & Time Collected 05/07/99 11:45:00 Category WATER

	RESULT	LIMIT			
Dichlorodifluoromethane	<u>nd</u>	10	Ethyl benzene	ND .	10
Chloromethane	ND	10	1,1,1,2-Tetrachloroethane	ND	10
Vinyl Chloride	ND	10	m+p-Xylene	<u>49.5</u> *_	10
Bromométhane	ND	<u>25</u>	o-Xylene	ND	10
Chloroethane	ND.	10	Styrene	ND	10
Trichlorofluoromethane	<u>QN</u>	10	Isopropyl benzene	<u>ND</u>	10
1,1-Dichloroethene	NO.	10	Bromoform	<u>ND</u>	10
Methylene Chloride	ND.	<u>10</u>	1,1,2,2-Tetrachloroethane	<u> GN</u>	10
trans-1,2-Dichloroethene	ND.	10	1,2,3-Trichloropropane	<u>ND</u>	10
1,1-Dichloroethane	ND	10	n-Propyl benzene	<u> </u>	10
2,2-Dichloropropane	<u> </u>	10	Bromobenzene	<u>ND</u>	10
cis-1,2-Dichloroethene	ND	10	1,3,5-Trimethyl benzene	<u>ND</u>	<u>10</u>
Chloroform	ND	10	2-Chlorotoluene	<u>ND</u>	<u>10</u>
Bromochloromethane	ND	10	4-Chlorotoluene	<u>ND</u>	10
1,1,1-Trichloroethane	<u>nd</u>	10	tert-Butyl benzene	<u>ND</u>	10
1,1-Dichloropropene	<u> </u>	10	1,2,4-Trimethylbenzene	ND	10
€arbon Tetrachloride	ND.	10	sec-Butylbenzene	<u> </u>	10
Benzene	294	10	p-Isopropyltoluene	<u>ND</u>	<u>10</u>
1,2-Dichloroethane	<u>ND</u>	<u>10</u>	1,3-Dichlorobenzene	<u>ND</u>	10
Trichloroethene	<u>ND</u>	10	1,4-Dichlorobenzene	<u>ND</u>	10
1,2-Dichloropropane	<u> </u>	10	n-Butylbenzene	<u>ND</u>	<u>10</u>
Bromodichloromethane	<u>nd</u>	10	1,2-Dichlorobenzene	<u>NO</u> .	10
Oibromomethane	<u>ND</u>	<u>25</u>	1,2-Dibromo-3-Chloropropane	<u> </u>	25
Toluene .	<u>95.5</u>	10	1,2,4-Trichlorobenzene	ND	10
1,1,2-Trichloroethane	<u> ND</u>	10	Hexachlorobutadiene	<u>nd</u> .	10
Tetrachloroethene	<u> </u>	10	Naphthalene	<u>817</u> ?	<u>10</u>
1,3-Dichloropropane	<u> </u>	10	1,2,3-Trichlorobenzene	ND	10
Dibromochloromethane	<u> ND</u>	10	Methyl-t-Butyl Ether	<u>ND</u>	25
1,2-Dibromoethane	ND	10			
Chlorobenzene	ND	<u>10</u>			
N	otes and Definit	ions for	this Report:	$MN_{i+j+j}$	

DATE RUN 05/14/99 ANALYST \_\_\_\_\_JPH INSTRUMENT \_\_\_\_\_D DILUTION 5 UNITS ug/L



D	n
Page	У

TOXIKON CORP. REPORT

Work Order # 99-05-206

Received: 05/11/99

Results by Sample

SAMPLE ID MW-3

FRACTION <u>04A</u> TEST CODE <u>GRO</u> NAME <u>GASOLINE RANGE ORGANICS</u> Date & Time Collected 05/07/99 11:45:00 Category WATER

		8015 MODIFIED GRO
•	ALIPHATICS AROMATICS	RESULT LIMIT  *  0.572
		Notes and Definitions for this Report:  DATE RUN 05/13/99  ANALYST NLC
		INSTRUMENT V5 DIL_FACTOR 2 UNITS = mg/L
		ND = not detected at detection limit

TOXIKON CORP.

REPORT

Work Order # 99-05-206

Received: 05/11/99

Results by Sample

SAMPLE ID MM-2	FRACTION <u>05A</u>	TEST CODE 8021M_	NAME <u>VOL.</u>	ORG. COMP.
	Date & Time Col	lected 05/07/99 12	2:00:00	Category WATER

	RESULT	LINIT			
Dichlorodifluoromethane	ND	10	Ethyl benzene	ИD	10
Chloromethane	ND ND	10	1,1,1,2-Yetrachloroethane	- ND	10
Vinyl Chloride	ND	10	m+p-Xylene	ND	10
Bromomethane	ND	25	o-Xylene	ND	10
Chloroethane	ND	10	Styrene	ND	10
Trichlorofluoromethane	ND	10	Isopropyl benzene	ND	10
1,1-Dichloroethene	MD	10	Bromoform	NO	10
Methylene Chloride		10	1,1,2,2-Tetrachloroethane	<u>GN</u>	10
trans-1,2-Dichloroethene	ND	10	1,2,3-Trichloropropane	ND	10
1,1-Dichloroethane	ND	10	n-Propyl benzene	ND	10
2,2-Dichloropropane	ND	10	Bromobenzene	ND	10
cis-1,2-Dichloroethene	ND	10	1,3,5-Trimethyl benzene	ND	10
Chloroform	ND	10	2-Chlorotoluene	ND	10
Bromochloromethane	ND	10	4-Chlorotoluene	ND	10
1,1,1-Trichloroethane	ND	10	tert-Butyl benzene	ND.	10
4,1-Dichloropropene	ND	10	1,2,4-Trimethylbenzene	<u>ND</u>	10
Carbon Tetrachloride	ND	10	sec-Butylbenzene	ND.	10
Benzene	ND	10	p-Isopropyltoluene	ND	10
1,2-Dichloroethane	ND	. 10	1,3-Dichlorobenzene	ND	10
Trichloroethene	ND.	10	1,4-Dichlorobenzene	ND	10
1,2-Dichloropropane	ND	10	n-Butylbenzene	ND	10
Bromodichloromethane	ND	10	1,2-Dichtorobenzene	ND	10
Dibromomethane	ND	25	1,2-Dibromo-3-Chloropropane	ND	<u>25</u>
Toluene .	<u>ND</u>	10	1,2,4-Trichlorobenzene	ND	10
1,1,2-Trichloroethane	<u>NĐ</u>	10	Hexachlorobutadiene	<u>ND</u>	<u>10</u>
Tetrachloroethene	<u>ND</u>	10	Naphthalene	<u>ND</u>	10
1,3-Dichloropropane	<u>ND</u>	10	1,2,3-Trichlorobenzene	<u>ND</u>	<u>10</u>
Dibromochloromethane	ND.	10	Methyl-t-Butyl Ether	372	· 25
1,2-Dibromoethane	ND	10			
Chlorobenzene	ND	<u>10</u>			

Notes and Definitions for this Report:

DATE RUN 05/13/99

ANALYST JPM

INSTRUMENT D

DILUTION 5

UNITS Ug/L

MIN S I THE

1000



Page 11 Received:		IKON CORP. Results by	REPORT Sample	¥ork Order # 99-05-206
SAMPLE ID	MJ-2	FRACTION <u>05A</u> Date & Time Col	TEST CODE <u>GRO</u>	NAME GASOLINE RANGE ORGANICS :00:00 Category WATER

٠.

	8015 MODIFIED GRO
	RESULT LIMIT
	*
ALIPHATICS	0.426 0.10
AROMATICS	<u>0.141</u> <u>0.10</u>
_	
_	- 10/4° · · · · · · · · · · · · · · · · · · ·
_	<del></del>
	Notes and Definitions for this Report:
	DATE RUN 05/12/99
	DATE RUN 05/12/99 ANALYST <u>CAL</u>
	DATE RUN         05/12/99           ANALYST         CAL           INSTRUMENT         V5
	DATE RUN 05/12/99 ANALYST <u>CAL</u>



Page 12

TOXIKON CORP.

REPORT

Work Order # 99-05-206

Received: 05/11/99

Test Methodology

TEST CODE 8021M NAME VOL. ORG. COMP.

**EPA METHOD 8021B** 

Reference: Test Methods for Evaluating Solid Waste Physical/Chemical Methods.

3rd Edition, SW846. Volatile Organic Compounds in Water by Purge . and Trap Capillary Column Gas Chromatography With Photoinoization

and Electrolyltic Conductivity Detectors in Series.

FINAL UPDATE 111, 1996.

TEST CODE GRO NAME GASOLINE RANGE ORGANICS

METHOD: EPA METHOD 8015 Modified; Gasoline Range Organics

Nonhalogenated Volatile Organics. Test Methods for Evaluating Solid Waste, Physical/Chemical Methods 3rd Edition, Final Update I.

Quantitation for BTEX/MTBE is performed by analysis on a PID detector. Miscellaneous aromatics eluting between o-xylene and 1,2,4-trimethylbenzene are quantitated on the PID detector using the response factor of o-xylene. Miscellaneous aliphatics eluting between 3-methylpentane and isooctane are quantitated on the FID detector using the response factor of n-hexane.

This method meets the specifications of Maine DEP Method 3.1.1.2.6

15 Wiggins Ave., Bedford, MA 01730 Telephone: (781) 275-3330 Fax: (781) 275-7478

# CHAIN OF CUSTODY RECORD

WORK ORDER #: 99-03 - 200 DUE DATE : 05-18 - 99

COMPANY: Lincoln Applied Goodogy									TYPE	CO	ONTAINER TYPE			ANALYSES										
ADDRESS: 163 Royal Rd  LIKOIN; UT 05443  PHONE #: (802 )453-4384 FAX #: (802 )453-5399  P.O. #:  PROJECT MANAGER: Rick Wardenberg  PROJECT ID/LOCATION: CFI Burlington								2. SOIL 3. SLUDG 4. OIL 5. DRINKII 6. WATER	WASTEWATER P-PLASTIC SOIL G-GLASS SLUDGE V-VOA															
TOXIKON #	SAMPLE IDENTIFICATION	SAMPLE	CO	NTAIN	IER		LING	PRESE	RVATIV	E		\$\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\										SPECIAL INSTRUCTIONS COMMENTS		
	Trip Blank	H20	40ml	V	4	5/7/4	0900	HCI	·	/	/		<b></b>											
<b>O</b>	mw-I	GW	40m)	V	4	5/7/19	1100	HC	<u> </u>	<b>~</b>	/							:						
3	mw-4	GW	40ml	V	4	5/1/9	1125	HC1		<u>/</u>	/													
4	Mw-3	GW	4cm1	V	4	5/7/99	1145	HCI		<u>~</u>	/						<u> </u>							
	MW-Z	CW	40ml	V	4	5/7/99	1200	HC		<u>/</u>	<u> </u>													
				<u> </u>						,-								<u> </u>		<u> </u>		<u> </u>		
																	ļ							
						ļ <b>.</b>	·																	
				_						··-··-										ļ		2		
					_		·	:		. <u> </u>										<u> </u>				
		<u> </u>	ļ			<u> </u>																		
				_		ļ																		
		1		<u> </u>		10111				L.,,				<u> </u>						<u> </u>	L			
SAMPLED BY: DATE: 5 - 7 - 99 QUOTATION  Jahe Peince TIME: 0900 - 1700 -					l #: 						<i>j</i>													
RELINQUISHED BY:		DATE: 5 - 10 - 99 RECEIVED B						Y: DATE: TIME:				-					☐ RUSH BUSINESS DAY TURN AROUND ☑ROUTINE							
RELINQU	ISHED BY:	DATE: 05-11 - 90 RECEIVED F					OR LAB BY: DATE: 05 - 1					//	- 9		Are th	Sample disposal information Are there any other known or suspected								
METHOD	O-EX OF SHIPMENT	COOLER						MPERATURE those listed above?																